



**Office of the Assistant Executive Engineer,
Public Works Department, Sub - Division Davanagere.**

Old P.B. Road, Davanagere

Telephone No. 08192-259676

Nos: AEE/PWD/S.D/DVG/AE-2/Stability/2025-26/ 367

Date : 25/07/2025

To,

Chairman/Principal,
Smt. Pushpa Shamanur Mahalingappa
Residential School,
Shamanur Education Trust (R),
No. 5335, 1st Main,
Swamy Vivekananda Extension,
Davanagere-577004.

Sir,


Sub:- Issue of building stability Certificate.

Ref:- Your office letter Dated: 17.07.2025.

With reference to the above subject and reference letter, the said building was inspected on 22.07.2025. It is certified that the building Taksha Shila block of Smt. Pushpa Shamanur Mahalingappa Residential School at No. 5335, 1st Main, Swamy Vivekananda Extension, Davangere is structurally stable. Proper maintenance of the school building should be done every year. This letter is issued with reference to above letter & Challan Number: CR0725005900111891, Dated: 08.07.2025.

- Enclosed : 1) Annexure D.
2) Fitness Certificate issued from
U.B.D.T. College, Davanagere
3) Photos.

Yours Faithfully,


Assistant Executive Engineer,
P.W.D. No:3, Sub - Division,
Davanagere.



Annexure D

BUILDING SAFETY CERTIFICATE

No.

Dated:

It is certified that the existing building Smt. Pushpa Shamanur Mahalingappa Residential School at No. 5335, 1st Main, Swamy Vivekananda Extension, Davangere-577004 is having block(s)/Floor(s) as per details below:

Detail of Block(s) in premises	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)
No. of Floor(s) in the Block (As per construction)	Taksha Shila Building consist Basement Floor & G + 5 Floors	Amaravathi G + 5 Floors	Chilipili B G + 5 Floors	Chilipili A G + 5 Floors	Nalanda G + 5 Floors
<ul style="list-style-type: none">For Taksha Shila block License taken from Corporation for Basement Floor & G + 4 floor only.The management/Authorities have not Produced license copy of remaining buildings in the premises.					

The building is owned/occupied by Smt. Pushpa Shamanur Mahalingappa Residential School. The University B.D.T. college of Engineering, Davanagere has been issued fitness certificate for Taksha Shila Block (Only). The building & said premises inspected by the officers of Public Works Department on 22-07-2025 in the presence of Chairman. The said Taksha Shila building is structurally fit for occupancy for running school with effect from 22-07-2025 for a period of 3 (Three) years.

At the time of visual Inspection following observations are made :

- The premises of Smt. Pushpa Shamanur Mahalingappa Residential School consisting of 1) Nalanda Block, 2) Chilipili A-Block, 3) Chilipili B-Block, 4) Amaravathi Block & 5) Taksha Shila Block from North end respectively.
- The Building Safety Certificate is requested by the Trust only for Taksha Shila Block.
- The High voltage Transmission lines passes in between Nalanda Block & Chilipili A-Block which are situated in the same premises where Taksha Shila Block exists.


Assistant Executive Engineer
No.3, P.W.D. Sub-Division, Davangere

- The High voltage Transmission lines passes about 7.40 mtr away from North – East corner & 3.40 mtr away from North – West corner at the side of Nalanda Block.
- The another High voltage Transmission lines passes about 5.50 mtr away from South – East corner & 9.80 mtr away from South – West corner at the side of Chilipili A-Block.
- The high tension line is about 63.00 mtrs away from the Taksha Shila block.
- The Building for which stability certificate sought exists at South end of the property that is at the side of Amaravathi Block.
- As per the fitness report given by the University B.D.T. college of Engineering, Davanagere, The Taksha Shila building seems satisfactory.
- The High voltage Transmission lines passes through the same premises of these buildings, is required to take necessary permission from KPTCL.
- The management/Authorities have not produced building approved plan, drawings, structural details, licenses and other necessary documents at the time of inspection except Taksha Shila Block.
- The storm water drain passes 5.00 mtrs away on south side of the Taksha Shila building compound. Flows through East to west direction.
- The Structural Safety Certificate is issued only for Taksha Shila Block subject to obtain NOC from KPTCL. If any hazards happen due to High voltage Transmission line, the School/Management/Authority is responsible.

Certificate Issued on 22-07-2025 at Davanagere By Assistant Executive Engineer, P.W.D., Sub Division, Davanagere.

Attachments : 1) Fitness Certificate of University B.D.T. College, Davanagere – 05 Pages.
2) Photos - 2 Pages.

Signature with Seal

:  Assistant Executive Engineer

No. 3, P.W.D. Sub-Division, Davanagere

 Name : Kumar C

Designation : Assistant Executive Engineer,

Name & Address of Department/ Office : Public Works Department.